

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start		Rating **	A	Issue No.	12
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals				
DWR ID	DWR_RD0070_01_f_2015_12				
Comment Code					
Inspector Comment					
The LMA has the O&M manuals.					

No Photos

LM Start		Rating **	A	Issue No.	13
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment				
DWR ID	DWR_RD0070_01_s_2013_13				
Comment Code					
Inspector Comment					
The LMA has adequate flood fight supplies and equipment.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start		Rating **	A	Issue No.	14
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training				
DWR ID	DWR_RD0070_01_s_2013_14				
Comment Code					
Inspector Comment					
The LMA completed flood fight training in 2014.					

No Photos

LM Start	0.76	Rating **	A/W	Issue No.	36
LM End	0.76	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	2017 Storm Damage		39.145240 °	39.145240 °	
			-121.842650 °	-121.842650 °	
DWR ID	DWR_RD0070_01_f_2017_36				
Comment Code					
Inspector Comment					
Levee Evaluation Comments Description: Site ID No:154 Site Designation:RD 70-03 Repair Type: Erosion Rating:Area of Concern Field Date:7/17/2017 Notes:					

Photo 1 of 3 : LEVAL\_SP\_2018\_154\_1686.jpg



<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey


LM Start	0.76	Rating **	A/W	Issue No.	36 (cont)	
LM End	0.76	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	2017 Storm Damage			39.145240 °	39.145240 °	
				-121.842650 °	-121.842650 °	
DWR ID	DWR_RD0070_01_f_2017_36					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:154						
Site Designation:RD 70-03						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:7/17/2017						
Notes:						

LM Start	<b>0.76</b>	Rating **	A/W	Issue No.	<b>36 (cont)</b>
LM End	<b>0.76</b>	Issue Type +	Ma	Location *	

Photo 2 of 3 : LEVAL\_SP\_2018\_154\_1687.jpg



Photo 3 of 3 : LEVAL\_SP\_2018\_154\_1688.jpg



\* Location  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	1.77	Rating **	M	Issue No.	32
LM End	1.77	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.151282 °	39.151282 °
				-121.855818 °	-121.855818 °
DWR ID	DWR_RD0070_01_f_2016_32				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0070\_29\_32\_20180305\_00009.jpg



View of the rodent holes along the waterside slope.

LM Start	3.72	Rating **	M	Issue No.	29
LM End	3.72	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.158183 °	39.158183 °
				-121.888397 °	-121.888397 °
DWR ID	DWR_RD0070_01_f_2016_29				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0070\_29\_29\_20180305\_00004.jpg



View of the ruts along the waterside slope.

LM Start	4.57	Rating **	C	Issue No.	34
LM End	4.57	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.167168 °	39.167168 °
				-121.899102 °	-121.899102 °
DWR ID	DWR_RD0070_01_s_2015_34				
Comment Code					
PR : Prunings					
Inspector Comment					
The prunings was removed from landside toe.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	6.18	Rating **	M	Issue No.	6
LM End	6.18	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.187481 °	39.187481 °
				-121.910852 °	-121.910852 °
DWR ID	DWR_RD0070_01_s_2012_6				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 2 : SP\_2018\_RD0070\_29\_6\_20180305\_00001.jpg



View of vehicle erosion along the waterside slope.

LM Start	<b>6.18</b>	Rating **	M	Issue No.	<b>6 (cont)</b>
LM End	<b>6.18</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP\_2018\_RD0070\_29\_6\_20180305\_00002.jpg



View of the vehicle erosion along the waterside slope.

LM Start	6.44	Rating **	M	Issue No.	35
LM End	6.44	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.190897 °	39.190897 °
				-121.912713 °	-121.912713 °
DWR ID	DWR_RD0070_01_s_2018_35				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Repair the rodent holes along the landside slope.					

Photo 1 of 1 : SP\_2018\_RD0070\_29\_35\_20180403\_00076.jpg



View of the rodent holes along the landside slope.

**\* Location**

LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	03/15/2018 03/15/2018	Bob Duffey

LM Start	6.57	Rating **	U	Issue No.	40
LM End	6.57	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.192283 °	39.192283 °
				-121.914388 °	-121.914388 °
DWR ID	DWR_RD0070_01_s_2018_40				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Repair the rodent holes along the landside slope.					

Photo 1 of 1 : SP\_2018\_RD0070\_29\_40\_20180403\_00077.jpg



View of rodent holes along the landside slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	<b>0.07</b>	Rating **	A/W	Issue No.	<b>74</b>
LM End		Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			39.193083 °	°
				-121.935258 °	°
DWR ID	DWR_RD0070_02_f_2017_74				
Comment Code					
Inspector Comment					
Levee Evaluation Comments Description: Site ID No:142 Site Designation:LMA-22 Repair Type: Erosion Rating:Area of Concern Field Date:6/7/2017 Notes: Problematic site was not found. No erosion observed.					

No Photos

LM Start	<b>2.40</b>	Rating **	M	Issue No.	<b>49</b>
LM End	<b>2.40</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.165462 °	39.165462 °
				-121.935244 °	-121.935244 °
DWR ID	DWR_RD0070_02_f_2016_49				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	3.46	Rating **	M	Issue No.	76
LM End	3.46	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.155008 °	39.155008 °
				-121.921905 °	-121.921905 °
DWR ID	DWR_RD0070_02_f_2017_76				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Repair the rodent holes along the waterside slope.					

Photo 1 of 1 : SP\_2018\_RD0070\_30\_76\_20180305\_00019.jpg



View of the rodent holes along the waterside slope.

LM Start	4.31	Rating **	M	Issue No.	51
LM End	4.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.144305 °	39.144305 °
				-121.917400 °	-121.917400 °
DWR ID	DWR_RD0070_02_f_2016_51				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	4.95	Rating **	M	Issue No.	54
LM End	4.95	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.142016 °	39.142016 °
				-121.926214 °	-121.926214 °
DWR ID	DWR_RD0070_02_f_2016_54				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0070\_30\_54\_20180305\_00006.jpg



View of the trees blocking visibility.

**\* Location**  
LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**  
A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	7.74	Rating **	N	Issue No.	59
LM End	7.74	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.124503 °	39.124503 °
				-121.915252 °	-121.915252 °
DWR ID	DWR_RD0070_02_f_2016_59				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

LM Start	8.10	Rating **	M	Issue No.	2
LM End	8.23	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			39.122459 °	39.120684 °
				-121.910121 °	-121.909152 °
DWR ID	DWR_RD0070_02_s_2016_2				
Comment Code					
Inspector Comment					
1997 - Critical Site - Erosion of cobble site on outside of a bend. Failure caused by erosion of a material from behind the cobbles and cobbles rolling down the slope. Failure is just above the toe levee. Some repairs had been done at the upstream end. 2004 - Some minor new erosion at the top of the berm. 2005 - Trees look okay and the downstream end has some new rock repair. Site is no longer critical. 2006 - No longer critical, some repairs. 2015: No observed changes. [2015 Site ID: SAC_130-0_L]					

Photo 1 of 1 : SP\_2018\_RD0070\_30\_2\_20180305\_00002.jpg



USACE 2013 Photo #1

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	8.10	Rating **	M	Issue No.	60
LM End	8.10	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.122568 °	39.122568 °
				-121.909723 °	-121.909723 °
DWR ID	DWR_RD0070_02_f_2016_60				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	9.28	Rating **	M	Issue No.	61
LM End	9.28	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.107285 °	39.107285 °
				-121.900753 °	-121.900753 °
DWR ID	DWR_RD0070_02_f_2016_61				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0070\_30\_61\_20180305\_00010.jpg



View of the rodent holes along the landside slope.

LM Start	9.69	Rating **	N	Issue No.	63
LM End	9.69	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.101343 °	39.101343 °
				-121.899381 °	-121.899381 °
DWR ID	DWR_RD0070_02_f_2016_63				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	11.07	Rating **	M	Issue No.	48
LM End	11.07	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.086098 °	39.086098 °
				-121.889988 °	-121.889988 °
DWR ID	DWR_RD0070_02_s_2018_48				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove the tree from the waterside slope and toe.					

Photo 1 of 1 : SP\_2018\_RD0070\_30\_48\_20180402\_00128.jpg



View of the tree along the waterside slope and oe

LM Start	13.82	Rating **	A/W	Issue No.	72
LM End	13.82	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.068370 °	39.068370 °
				-121.862763 °	-121.862763 °
DWR ID	DWR_RD0070_02_s_2017_72				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Repair the erosion along the waterside slope.					

Photo 1 of 1 : SP\_2018\_RD0070\_30\_72\_20180305\_00015.jpg



View of the erosion along the waterside slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	13.83	Rating **	A/W	Issue No.	75
LM End	13.83	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			39.068190°	39.068190°
				-121.862700°	-121.862700°
DWR ID	DWR_RD0070_02_f_2017_75				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:152					
Site Designation:RD 70-01					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:7/17/2017					
Notes: bank slope erosion around a drainage pipe/box					

Photo 1 of 3 : LEVAL\_SP\_2018\_152\_1717.jpg



LM Start	<b>13.83</b>	Rating **	A/W	Issue No.	<b>75 (cont)</b>
LM End	<b>13.83</b>	Issue Type +	Ma	Location *	

Photo 2 of 3 : LEVAL\_SP\_2018\_152\_1728.jpg



<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2018

### Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	03/15/2018 03/15/2018	Bob Duffey

LM Start	13.83	Rating **	A/W	Issue No.	75 (cont)	
LM End	13.83	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			39.068190°	39.068190°	
				-121.862700°	-121.862700°	
DWR ID	DWR_RD0070_02_f_2017_75					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:152						
Site Designation:RD 70-01						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:7/17/2017						
Notes: bank slope erosion around a drainage pipe/box						

Photo 3 of 3 : LEVAL\_SP\_2018\_152\_1730.jpg



LM Start	14.14	Rating **	M	Issue No.	66
LM End	14.14	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.069849 °	39.069849 °
				-121.857267 °	-121.857267 °
DWR ID	DWR_RD0070_02_f_2016_66				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					

Photo 1 of 1 : SP\_2018\_RD0070\_30\_66\_20180305\_00013.jpg



View of slope instability along the landside slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---